













B _{AB}		1	R ₁₀		1
C _{AC}		2	S ₁₁		1
D _{AD}		1	T _A		15
E _{AE}		1	U _B	 M6x40 mm	9
F _{AF}		2	V _C	 M6x40 mm	2
G _{AG}		4	W _D	 M6x60 mm	2
H _{AH}		4	X _E	 M3,5x16 mm	28
I ₁		2	Y _F	 M4x25 mm	1
J ₂		2	Z _G	 M4x32 mm	38
K ₃		2	Z _{1H}	 M4x50 mm	16
L ₄		4	Z _{2I}		2
M ₅		4	Z _{3J}		6
N ₆		1	Z _{4K}		6
O ₇		1	Z _{5L}		6
P ₈		1	Z _{6M}		24
Q ₉		1	Z _{8N}		9

A _{AA}		1
-----------------	--	---






24



25



26

