










Part List

A		x 1
B		x 1
C		x 2
D		x 4
E		x 5
F		x 1
G		x 1


Hardware List

a		x16
b		x 5
c		x16
d		x 8
e		x 8
f		x 8
g		x 26
h		x 5
i		x 2
j		x 4


Step 01



Step 02



Step 03



Step 04

