







① x1




② x1



③ x4


A



M6x16mm

x4

B



M6x30mm

x8


C



M6mm

x8

D



M6mm


x12

E




x1

F







x4

G






x8




1.






2.







3.



4.



5.



6.

